



Span2 east side looking SE

Latitude:46.35666, Longitude:-101.29901


Route:00031 Log:29.208

District 61, Grant County

Owner: 1-State Highway Agency

Team Leader: Jake Mertz

Approved By: Jake Mertz



46.35666, -101.29901

| IDENTIFICATION | |
|---|--------------------------|
| (1) State Names | North Dakota |
| (8) Structure Number | 0031-029.214 |
| (5) Inventory Route | 00031 |
| (2) Highway Agency District | 61 |
| (3) County Code | Grant, North Dakota |
| (4) Place Code | 0 |
| (6) Features Intersected | DOG TOOTH CREEK |
| (7) Facility Carried | ND HIGHWAY 31 |
| (9) Location | RALEIGH |
| (11) Mile Point | 29.208 mi |
| (12) Base Highway Network | Yes |
| (13) LRS Inventory Rte | 0000000000 |
| (16) Latitude | 46.35666 |
| (17) Longitude | -101.29901 |
| GPS X | 323131.3 |
| GPS Y | 5136244.5 |
| (98) Border Bridge State Code | -1 |
| (99) Border Bridge Struct. No. | — |
| STRUCTURE TYPE AND MATERIAL | |
| (43) Main Structure Type | 21 |
| Material | 2-Concrete continuous |
| Type | 1-Slab |
| (44) Approach Structure Type | 00 |
| Material | 0-Other |
| Type | 0-Other |
| (45) No. of Spans in Main Unit | 2 |
| (46) No. of Approach Spans | 0 |
| Culvert | |
| (107) Deck Structure Type | 1-Concrete Cast-in-Place |
| (108) Wearing Surface/Protective System | |
| Type of Wearing Surface | 6-Bituminous |
| Type of Membrane | 0-None |
| Type of Deck Protection | 0-None |
| Deck overburden | 32 |
| AGE AND SERVICE | |
| (27) Year Built | 1957 |
| (106) Year Reconstructed | |
| (42) Type of Service | 15 |
| On | 1-Highway |
| Under | 5-Waterway |
| (28) Lane | |
| On | 2 |
| Under | 0 |
| (29) Average Daily Traffic | 390 |
| (30) Year of ADT | 2019 |
| (109) Truck ADT | 15 % |
| (19) Bypass, Detour Length | 45 mi |
| (114) Future ADT | 300 |
| (115) Year of Future ADT | 2039 |
| GEOMETRIC DATA | |
| (48) Length of Maximum Span | 20 ft |
| (49) Structure Length | 42 ft |
| (50) Curb or Sidewalk Width | |
| Left | 0 ft |
| Right | 0 ft |
| (51) Bridge Roadway Width Curb to Curb | 27.9 ft |
| (52) Deck Width Out to Out | 33.1 ft |
| (32) Approach Roadway Width (W/Shoulders) | 34.1 ft |
| (33) Bridge Median | 0-No median |
| (34) Skew | 0 Deg |
| (35) Structure Flared | No flare |
| (10) Inventory Route Min Vert Clear | 99.99 ft |
| (47) Inventory Route Total Horiz Clear | 27.2 ft |
| (53) Min Vert Clear Over Bridge Rdwy | 99.99 ft |
| (54) Min Vert Underclear | 0 ft |
| Ref: | |
| (55) Min Lat Underclear RT | 99.9 ft |
| Ref: | |
| (56) Min Lat Underclear LT | 0 ft |

| CLASSIFICATION | |
|---|--|
| (A-7) Agency Admin Area | 1 |
| (112) NBIS Bridge Length | Y |
| (104) Highway System | Non-NHS |
| (26) Functional Class | 6-Rural Minor Arterial |
| (100) Defense Highway | 0-The inventory route is not a S |
| (A16) TE Route | |
| (101) Parallel Structure | N-No parallel structure exists. |
| (102) Direction of Traffic | 2 - way traffic |
| (103) Temporary Structure | |
| (105) Federal Lands Highways | 0-N/A |
| (110) Designated National Network | 0-The inventory route is not part of |
| (20) Toll | 3-On free road. The structure is toll- |
| (21) Maintain | 1-State Highway Agency |
| (22) Owner | 1-State Highway Agency |
| (37) Historical Significance | 5-Bridge is not eligible for the NRHP |
| CONDITION | |
| (58) Deck | 4 |
| (59) Superstructure | 5 |
| (60) Substructure | 7 |
| (61) Channel & Channel Protection | 5 |
| (62) Culverts | N |
| LOAD RATING AND POSTING | |
| (31) Design Load | 5-MS 18 / HS 20 |
| (63) Operating Rating Method | 1 |
| (64) Operating Rating | 47.4 |
| (65) Inventory Rating Method | 1-Load Factor(LF) |
| (66) Inventory Rating | 25.6 |
| (70) Bridge Posting | 5-Equal to or above legal loads |
| (41) Structure Open/Posted/Closed | A-Open, no restriction |
| APPRAISAL | |
| (67) Structural Evaluation | 6 |
| (68) Deck Geometry | 6 |
| (69) Clearances, Vertical/Horizontal | N |
| (71) Waterway Adequacy | 6 |
| (72) Approach Roadway Alignment | 7 |
| (36) Traffic Safety Features | 1111 |
| A) Bridge Railings | 1-Inspected feature meets currently a |
| B) Transitions | 1-Inspected feature meets currently a |
| C) Approach Guardrail | 1-Inspected feature meets currently a |
| D) Approach Guardrail Ends | 1-Inspected feature meets currently a |
| (113) Scour Critical Bridges | 5-Bridge foundations determined to be |
| APPROVED INSPECTIONS | |
| (90) Inspection Date | 05/2021 |
| (91) Frequency | 24 Months |
| (92) Critical Feature Inspection | Req Freq. (Mon) Date |
| A: Fracture Critical Detail | No |
| B: Underwater Inspection | No |
| C: Other Special Inspection | Yes 0 09/2021 |
| NAVIGATION DATA | |
| (38) Navigation Control | 0-No navigation control on water |
| (111) Pier Protection | - |
| (39) Navigation Vertical Clearance | 0 ft |
| (116) Vert-Lift Bridge Nav Min Vert Clr | ft |
| (40) Navigation Horizontal Clearance | 0 ft |
| AGENCY ITEMS | |
| (A-21) Fedaid Project no. | S-1-031(00)029 |
| (A-14) Chaining Date | |
| (A-15) Delamination Pct | |
| (A-2) Rating Date | 4/24/2017 12:00:00 AM |
| Bridge Health Index | 43.03 |

Inspection Team Lead: Jake Mertz

| ELEM | DESCRIPTION | UNITS | TOTAL | CS1 | CS2 | CS3 | CS4 |
|---|------------------------------------|-------|-------|-----|-----|------|-----|
| 38 | RC Slab | SF | 1173 | 0 | 0 | 1173 | 0 |
| 1130 | Cracking (RC and Other) | SF | 1173 | 0 | 0 | 1173 | 0 |
| 510 | Wearing Surfaces | SF | 1173 | 460 | 500 | 213 | 0 |
| 3210 | Delam/Spall/Patched Area/Pothole | SF | 213 | 0 | 0 | 213 | 0 |
| 3220 | Crack (Wearing Surface) | SF | 500 | 0 | 500 | 0 | 0 |
| (38-1130) | | | | | | | |
| The entire underside of the deck on both spans is map cracked with efflorescence. 4May2021 | | | | | | | |
| (38-510-3210) | | | | | | | |
| patching on deck - 4/23/2019 | | | | | | | |
| There is a 3 foot by 60 foot area along the east curb and a 11 foot by 3 foot area at the north end in the South bound lane that is spalled. 4May2021 | | | | | | | |
| (38-510-3220) | | | | | | | |
| There is cracking of the asphalt wearing surface throughout the deck. 4May2021 | | | | | | | |
| 210 | Reinforced Concrete Pier Wall | LF | 56 | 38 | 18 | 0 | 0 |
| 1120 | Efflorescence/Rust Staining | LF | 15 | 0 | 15 | 0 | 0 |
| 1130 | Cracking (RC and Other) | LF | 3 | 0 | 3 | 0 | 0 |
| (210-1120) | | | | | | | |
| The outer areas of the pier 2 pier wall have efflorescence. 4May2021 | | | | | | | |
| (210-1130) | | | | | | | |
| some efflorescence - 4/23/2019 | | | | | | | |
| There are 3 cracks in the pier 2 pier wall. 4May2021 | | | | | | | |
| 215 | Reinforced Concrete Abutment | LF | 66 | 61 | 5 | 0 | 0 |
| 1130 | Cracking (RC and Other) | LF | 5 | 0 | 5 | 0 | 0 |
| (215-1130) | | | | | | | |
| diagnol cracking - 4/23/2019 | | | | | | | |
| The abutments have a total of 5 cracks that range from approximately 0.010 to 0.012 in width. 4May2021 | | | | | | | |
| 331 | Reinforced Concrete Bridge Railing | LF | 85 | 0 | 80 | 5 | 0 |
| 1130 | Cracking (RC and Other) | LF | 25 | 0 | 20 | 5 | 0 |
| 1190 | Abrasion/Wear (PSC/RC) | LF | 60 | 0 | 60 | 0 | 0 |
| (331-1130) | | | | | | | |
| East curb has horizontal cracking and spalling - 4/23/2019 | | | | | | | |

Team Lead: Jake Mertz, **Inspection Date:** September 28, 2021

[illegible]

Inspection Comments


4/23/19- ALL CURBS HAVE MINOR CRACKS. 3 HAIRLINE VERTICAL CRACK ON PIER 2, CURBS HAVE SOME DAMAGE FROM WHAT LOOKS LIKE SNOW REMOVAL EQUIPMENT. 2 LONGITUDINAL HAIRLINE CRACKS UNDERSIDE OF DECK CONTINUOUS THRU PIER. 50% of the underside of the deck has map cracking with efflorescence. Deck has a 2" asphalt overlay on it. - 4/23/2019

Significant Findings

There are large spalls on the slab in the wearing surface and the underside of the deck is map cracked with efflorescence. There are large horizontal cracks on the outside faces of the slab. The largest measuring approximately 0.060 in width.
4May2021




Span 2 next to North Abutment looking West




Span 2 West side looking towards Pier 2



Span 2, 3 feet from North. Abutment



Span 2 on North side of Pier 2



Span2 east side on north side pier2

Span 2 East side on North side of Pier 2



East side looking South

East side looking South



Southbound lane North end



Span 1 East side looking North



Span 1 Middle looking North



Span 1 West side looking North



Span 1 looking North West side



Span 1 East side Close view



Span 1 looking West



Span 1 looking South East side



Span 1 looking South West side



Deck wearing surface



NB lane wearing surface spalls



West face slab crack about pier .060



East face slab cracks horizontal

East face slab cracks horizontal



West face slab cracks

West face slab cracks



Looking SE



Looking north



Looking west



Looking south



Looking east



West face

CHANNEL PROFILE
North Dakota Department of Transportation, Bridge
SFN 17336 (7-2016)

Structure Number: 0031-029.214 Date: 5/4/2021 Inspector's Name: Michael Mente

STREAM CROSS SECTION
NOTE: Stream profile is to be taken on both sides of the bridge. Check appropriate directions.

Profile 1 taken on ☐ N ☐ S ☐ E ☒ W side of bridge, from ☒ N to S ☐ W to E
Measurements taken from top of ☐ Curb ☒ Rail ☐ Deck
Measurements taken at 9.5 intervals (ft.)
Measurements are as follows: 0.5 = 10.9 9.5 = 11.7 19 = 11.4 28.5 = 11.4 38 = 11.7

Profile 2 taken on ☐ N ☐ S ☒ E ☐ W side of bridge, from ☐ N to S ☐ W to E
Measurements taken from top of ☐ Curb ☒ Rail ☐ Deck
Measurements taken at 9.5 intervals (ft.)
Measurements are as follows: 0.5 = 10.7 9.5 = 11.6 19 = 11.8 28.5 = 11.6 38 = 11.3

| Evidence of Scour at Bridge | Yes | No | NA | Existing Channel Condition | Yes | No | NA |
|-------------------------------------|--------------------------|-------------------------------------|--------------------------|---|-------------------------------------|-------------------------------------|--------------------------|
| Channel slopes washing or sloughing | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Are channel banks up and downstream of bridge stable? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Scour holes near abutments | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Is the channel degrading/aggrading up or downstream? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Scour holes near piers | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Is the structure on a channel change? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Silt deposits downstream | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Are there lakes, reservoirs, dams, etc., near the crossing? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Obstruction of footings | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Does the channel appear to be moving laterally in the area of the bridge? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Debris collection | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | | |
| Cap (if any) displaced | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | | |

| Substructure Condition (Below Waterline) | Yes | No | NA | Substructure Condition (Below Waterline) | Yes | No | NA |
|--|--------------------------|--------------------------|--------------------------|--|--------------------------|--------------------------|--------------------------|
| Abutment scaling? | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Is there exposed piling below footing? | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Abutment spalling? | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Are there cracks? | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Is exposed rebar? | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Is there section loss on members? | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

If answered to any of the questions, measurements should be taken. Also, include sketches along with dimensions when applicable. These deficiencies shall be reflected in the rating of item 60. If these questions can not be answered, notify Bridge Engineer.

Take pictures or draw sketches of any and all factors contributing to scour or movement of the channel or streambed. Some factors are, but are not limited to, inadequate waterway area, ice jams/floes, debris, and channel/structures alignment. Give scour hole dimensions.

Remarks or explanations for the above items below. Use an additional page if necessary.

Channel profile



West face slab crack about pier .060



East face slab cracks horizontal

East face slab cracks horizontal



West face slab cracks

West face slab cracks



NB lane wearing surface spalls



Deck wearing surface


Deck wearing surface



Deck wearing surface




NB lane wearing surface spalls



South face pier wall cracks



Pier 2 north face crack



Pier 2 north face crack



East face slab cracks horizontal



.012 south abutment crack



Abutment 3 crack .010



East conc rail crack bigger then .100



East conc rail cracks



West curb crack .010



East curb abrasion



NW wing cracks .006

Maintenance Needs

Date Reported: 05/18/2021
Priority: Normal
Type of Work: ----- Other -----
Status: Unknown
Component: 331 - Reinforced Concrete Bridge Railing

Deficiency Description

There are cracks on the curb that need to be sealed.

Remarks

Recommend sealing the curb cracks. 4May2021



East conc rail crack bigger then .100



East conc rail cracks

Date Reported: 05/18/2021
Priority: Normal
Type of Work: Maintain General Safety Features
Status: Unknown
Component: Approach

Deficiency Description

The southeast guardrail has impact damage with broken posts.

Remarks

Recommend replacing the guardrail and broken posts. 4may2021



SE guardrail damage 3 post broke