



# DDIR Web Based Reporting System

2011



The DDIR Web based reporting system can be found at  
<http://www.dot.nd.gov/dotnet2/ddir/login.aspx>

At the login page, enter username and password to access system, if you need a username and password contact Bryon Fuchs at 328-2516 or [blfuchs@nd.gov](mailto:blfuchs@nd.gov)



On this page, the user can create a new DDIR By clicking on the link below



[Create New Detailed Damage Inspection Report \(DDIR\)](#)

Under Action, the user can view, edit or delete a previously created DDIR. Only DDIRs with no cost information entered can be deleted

Report Number	District	County	Damage Summary	Status	Total Cost	Action	Emergency Repairs	Permanent Repairs
12-2	Williston	DIVIDE	Roadway is inundated	Submitted	\$2,253,976.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-01	Bismarck	BURLEIGH	Test Damage Summary	Submitted	\$561,892.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-010101	Grand Forks	GRAND FORKS	Damage Summary entry portion.	Active	\$0.00	<a href="#">View</a>   <a href="#">Edit</a>   <a href="#">Delete</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-010A	Grand Forks	BURKE	Roadway and culvert washed out.	Active	\$275,000.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-01A	Valley City	STUTSMAN	Water washed away part of roadway.	Submitted	\$13,805.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-1	Fargo	CASS	Culvert and portion of highway 2 roadway washed away.	Submitted	\$177,850.39	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-102	Grand Forks	GRAND FORKS	Damage Summary Test Entry	Active	\$0.00	<a href="#">View</a>   <a href="#">Edit</a>   <a href="#">Delete</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-2	Grand Forks	GRAND FORKS	Bridge damaged due to ice jam.	Active	\$4,500.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-3	Bismarck	BURLEIGH	Roadway inundated by water.	Submitted	\$165,677.50	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-4	Bismarck	MORTON	Culvert full of ice caused roadway to be washed away.	Active	\$16,165.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-5	Bismarck	GRANT	Culvert washed away.	Active	\$251,255.44	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
30-01	Bismarck	MORTON	Sheet flow over road caused wash out	Active	\$35,000.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>

Under Emergency Repairs or Permanent Repairs the user can enter the quantities and costs of the completed and remaining repairs for each ER site

Detailed Damage Inspection Report Details

<b>*Company Name:</b>	<input type="text"/>
<b>*Report Number:</b>	<input type="text"/>
<b>*Status:</b>	Active <input type="text"/>
<b>*Damage Category:</b>	<input type="text"/>
<b>*Damage Type:</b>	<input type="text"/>
<b>*District:</b>	<input type="text"/>
<b>*County:</b>	<input type="text"/>
<b>*Inspection Date:</b>	<input type="text"/> (mm/dd/yyyy)
<b>City:</b>	<input type="text"/>
<b>*FA-Route:</b>	<input type="text"/>
<b>*Route Name:</b>	<input type="text"/>
<b>Mile Post:</b>	<input type="text"/>
<b>Structure No:</b>	<input type="text"/>
<b>*Location:</b>	<input type="text"/>
<b>*Damage Summary:</b>	<input type="text"/> Enter a Brief Summary of the Damages for the Site
<b>*Detailed Damages:</b>	<input type="text"/>

On this page the user will enter the basic information for each ER site

Location needs to include legal and generic description

In the Detailed Damages field, enter detailed information regarding specific damage at the site. Enter anything unusual or unique that is specific to the site. You also need specify what work was completed as PERMANENT RESTORATION COMPLETED CONCURRENTLY WITH EMERGENCY REPAIRS.

Return Add  
\*Required

Once all information has been added, hit Add at the bottom left of the page. This will take you back to the previous page where the emergency and permanent costs can be added

# DDOT Detailed Damage Inspection Reporting (DDIR)



Now that you've entered the DDIR site information, click on the category you want to add cost information to

[Create New Detailed Damage Inspection Report \(DDIR\)](#)

Report Number	District	County	Damage Summary	Status	Total Cost	Action	Emergency Repairs	Permanent Repairs
12-2	Williston	DIVIDE	Roadway is inundated	Submitted	\$2,253,976.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-01	Bismarck	BURLEIGH	Test Damage Summary	Submitted	\$561,892.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-010101	Grand Forks	GRAND FORKS	Damage Summary entry portion.	Active	\$0.00	<a href="#">View</a>   <a href="#">Edit</a>   <a href="#">Delete</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-010A	Grand Forks	BURKE	Roadway and culvert washed out.	Active	\$275,000.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-01A	Valley City	STUTSMAN	Water washed away part of roadway.	Submitted	\$13,805.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-1	Fargo	CASS	Culvert and portion of highway 2 roadway washed away.	Submitted	\$177,850.39	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-102	Grand Forks	GRAND FORKS	Damage Summary Test Entry	Active	\$0.00	<a href="#">View</a>   <a href="#">Edit</a>   <a href="#">Delete</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-2	Grand Forks	GRAND FORKS	Bridge damaged due to ice jam.	Active	\$4,500.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-3	Bismarck	BURLEIGH	Roadway inundated by water.	Submitted	\$165,677.50	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-4	Bismarck	MORTON	Culvert full of ice caused roadway to be washed away.	Active	\$16,165.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-5	Bismarck	GRANT	Culvert washed away.	Active	\$251,255.44	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
30-01	Bismarck	MORTON	Sheet flow over road caused wash out	Active	\$35,000.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>

# Detailed Damage Inspection Reporting (DDIR)

Main » Completed Emergency Repairs User: Kent Leben Logout

Completed Emergency Repairs Summary

Company Name:	ND Department of Transportation
Report No:	30-01
Method of Work:	<input type="text"/>
Estimated Construction Engineering:	\$0.00
Total Emergency Repairs Completed:	\$0.00

**Choose the method of work and enter CE and PE costs if applicable**

**The total emergency repairs field will update once you hit save**

[Create New Completed Emergency Repair Item](#)  **Click on the link here to add a new repair item**

Completed Repair Items

# NDDOT Detailed Damage Inspection Reporting (DDIR)

Main » Add Completed Emergency Repairs

User: Kent Leben Logout

### Completed Emergency Repairs Summary

<b>Company Name:</b>	ND Department of Transportation
<b>Report No:</b>	30-01
<b>Method of Work:</b>	Local Forces
<b>Estimated Construction Engineering:</b>	\$0.00
<b>Total Emergency Repairs Completed:</b>	\$0.00

### Add New Repair Items

<b>*Description:</b>	
<b>Units:</b>	302 - 0315: TRAFFIC SERVICE AGGREGATE SURFACE COURSE (TON)
<b>*Unit Price:</b>	302 - 0316: TRAFFIC SERVICE GRAVEL (CY)
<b>*Quantity:</b>	302 - 0318: AGGREGATE SURFACE COURSE CL 4 (TON)
<b>Cost:</b>	302 - 0320: AGGREGATE SURFACE COURSE CL 5 (TON)
	302 - 0321: AGGREGATE SURFACE COURSE CL 5 (CY)
	302 - 0335: AGGREGATE SURFACE COURSE CL 8 (TON)
	302 - 0336: AGGREGATE SURFACE COURSE CL 8 (CY)
	302 - 0337: AGGREGATE SURFACE COURSE CL 8-STOCKPILED (TON)
	302 - 0338: AGGREGATE SURFACE COURSE CL 8-SCREENED (TON)
	302 - 0339: AGGREGATE SURFACE COURSE CL 8-SCREENED (CY)
	302 - 0354: AGGREGATE SURFACE COURSE CL 12-SCREENED (CY)
	302 - 0355: AGGREGATE SURFACE COURSE CL 12 (TON)
	302 - 0356: AGGREGATE SURFACE COURSE CL 13 (TON)
	302 - 0357: AGGREGATE SURFACE COURSE CL 13 (CY)
	302 - 0380: TRIMMING BASE COURSE (SY)
	302 - 0390: RELAY SALVAGE-BASE COURSE (MILE)
	302 - 0399: SCORIA SURFACE COURSE (CY)
	302 - 0400: SALVAGE & RELAY SCORIA SURFACE COURSE (CY)
	302 - 0401: SALVAGE & RELAY AGGREGATE SURFACE COURSE (TON)
	302 - 0402: SALVAGE & RELAY AGGREGATE SURFACE COURSE (MIL)
	302 - 0403: AGGREGATE SURFACE COURSE (TON)
	302 - 0404: AGGREGATE SURFACE COURSE (CY)
	302 - 0405: SALVAGE & RELAY AGGREGATE SURFACE COURSE (CY)
	302 - 0407: RESHAPE AGGREGATE BASE COURSE (STA)
	302 - 0408: RESHAPE AGGREGATE BASE COURSE-SHOULDER (MILE)
	302 - 0409: AGGREGATE BASE COURSE REPAIR (MILE)
	302 - 0410: SALVAGE & RELAY AGGREGATE BASE COURSE (MILE)
	302 - 0411: SALVAGE & RELAY AGGREGATE BASE COURSE 3IN (MILI)
	302 - 0412: SALVAGE & RELAY AGGREGATE BASE COURSE 6IN (MILI)
	302 - 0413: REMOVE & RELAY 5IN AGGREGATE BASE COURSE (MILE)

Use the drop down box to select the item by spec and code.

# Detailed Damage Inspection Reporting (DDIR)

Main » Add Completed Emergency Repairs User: Kent Leben Logout

## Completed Emergency Repairs Summary

<b>Company Name:</b>	ND Department of Transportation
<b>Report No:</b>	30-01
<b>Method of Work:</b>	Local Forces
<b>Estimated Construction Engineering:</b>	\$0.00
<b>Total Emergency Repairs Completed:</b>	\$0.00

## Add New Repair Items

<b>*Description:</b>	302 - 0316: TRAFFIC SERVICE GRAVEL (CY)
<b>Units:</b>	CY
<b>*Unit Price:</b>	25.00
<b>*Quantity:</b>	100
<b>Cost:</b>	2500

After you've selected the item, enter the Unit Price and Quantity. Click **Add** to save and add the item and return to the previous page.

\*Required



# NDDOT Detailed Damage Inspection Reporting (DDIR)

Main » Completed Emergency Repairs

User: Kent Leben Logout

### Completed Emergency Repairs Summary

<b>Company Name:</b>	ND Department of Transportation
<b>Report No:</b>	30-01
<b>Method of Work:</b>	Local Forces
<b>Estimated Construction Engineering:</b>	\$0.00
<b>Total Emergency Repairs Completed:</b>	\$2,500.00

Save

**Repeat the process until all items for the chosen category of work (emergency or permanent) are added and hit Save, and then Return to Main**

[Create New Completed Emergency Repair Item](#)

### Completed Repair Items

Description	Units	Price	Quantity	Cost	Action
302 - 0316: TRAFFIC SERVICE GRAVEL (CY)	CY	\$25.00	100	\$2,500.00	<a href="#">Edit</a>   <a href="#">Delete</a>

Return to Main

User Maintenance

[Add User](#)  
[Search Users](#)

Search Criteria

Company:	<input type="text"/>
FHWA Disaster No:	<input type="text"/>
District:	<input type="text"/>
County:	<input type="text"/>

Once you've added all the necessary items under permanent and emergency repairs, to submit the DDIR click on **Edit** for your chosen site

[Create New Detailed Damage Inspection Report \(DDIR\)](#)

Report Number	District	County	Damage Summary	Status	Total Cost	Action	Emergency Repairs	Permanent Repairs
12-2	Williston	DIVIDE	Roadway is inundated	Submitted	\$2,253,976.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-01	Bismarck	BURLEIGH	Test Damage Summary	Submitted	\$561,892.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-010101	Grand Forks	GRAND FORKS	Damage Summary entry portion.	Active	\$0.00	<a href="#">View</a>   <a href="#">Edit</a>   <a href="#">Delete</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-010A	Grand Forks	BURKE	Roadway and culvert washed out.	Active	\$275,000.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-01A	Valley City	STUTSMAN	Water washed away part of roadway.	Submitted	\$13,805.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-1	Fargo	CASS	Culvert and portion of highway 2 roadway washed away.	Submitted	\$177,850.39	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-102	Grand Forks	GRAND FORKS	Damage Summary Test Entry	Active	\$0.00	<a href="#">View</a>   <a href="#">Edit</a>   <a href="#">Delete</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-2	Grand Forks	GRAND FORKS	Bridge damaged due to ice jam.	Active	\$4,500.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-3	Bismarck	BURLEIGH	Roadway inundated by water.	Submitted	\$165,677.50	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-4	Bismarck	MORTON	Culvert full of ice caused roadway to be washed away.	Active	\$16,165.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
11-5	Bismarck	GRANT	Culvert washed away.	Active	\$251,255.44	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>
30-01	Bismarck	MORTON	Sheet flow over road caused wash out	Active	\$37,500.00	<a href="#">View</a>   <a href="#">Edit</a>	<a href="#">Completed</a>   <a href="#">Remaining</a>	<a href="#">Permanent</a>

DDIR - Edit Detailed Damage Inspection Report - Windows Internet Explorer  
http://www.dot.nd.gov/dotnet2/ddir/ddirmaintenance.aspx?action=edit

File Edit View Favorites Tools Help | Convert Select

DDIR - Edit Detailed Damage Inspection Report

North Dakota nd.gov Official Portal for North Dakota State Government  
NDDOT North Dakota Department of Transportation  
Detailed Damage Inspection Reporting (DDIR)

Main » Edit DDIR User: Kent Leben Logout

Detailed Damage Inspection Report Details

*Company Name:	Heartland Engineering, Inc.
*Report Number:	11-010A
*Status:	Active
*Damage Category:	Active Submitted Road
*Damage Type:	Completed
*District:	Grand Forks
*County:	BURKE
*Inspection Date:	02/23/2011 (mm/dd/yyyy)
City:	Grand Forks
*FA-Route:	Interstate
*Route Name:	I-29
Mile Post:	
Structure No:	
*Location:	Water washed away culvert on I-29 south of Grand Forks
*Damage Summary:	Roadway and culvert washed out.
*Detailed Damages:	Roadway and culvert washed away south of I-29 impeding northbound traffic.

Click the drop down for status and select Submitted. Once the DDIR is submitted either Local Government or Maintenance Division will review it. If everything looks good it will be forwarded on to FHWA for review. If there are problems, the status will be changed back to active so the person who entered the information can make changes.

All supporting documentation, photographs and hydraulic analysis (if applicable) need to be submitted to the NDDOT FTP site and you must notify either Maintenance or Local Govt' division so it can be included with the DDIR when it is submitted to FHWA