

Intersection and/or Urban Crash Summary Sheets



Total Crashes: 37 (Sorted by Date)
 City: US 83 & ND 23
 Location: US 83 & ND 23
 Start - End Date: 1/1/2015 - 12/31/2024 (10 Years)

23 USC § 407 Documents
 NDDOT Reserves All Objections

- LEGEND**
- ▶ Fatal
 - ▶ Incapacitating Injury
 - ▶ Non-Incapacitating Injury
 - ▷ Possible Injury
 - ◆ Wet surface
 - ❄ Snow, Ice, Slush, Frost
 - ▲ Crash related to work zone
 - ① Unit number

- 1. Contributing Factor**
 * = alcohol or drugs involved
- 2. Most Harmful Event**
 For single vehicle crashes, the most harmful event is shown in parentheses in the "Type of Collision" column

Crash No.	Crash Severity Date, Day Surface Conditions, Weather Lighting, Time	Type of Collision	① AGE SEX CITY STATE Unit Configuration Movement (traffic control) Contributing Factor ¹ Most Harmful Event ²	②	Shortened Narrative	Diagram
1 322619	PDO 02/25/15 Wednesday Dry Clear Daylight 4:44 PM	Angle	① 30M MINOT ND Pickup - Van - Utility EB Turning Left (Stop) Care Required	② 67M MINOT ND Pickup - Van - Utility NB Going Straight	East intersection	→ ↑
2 325765	▶ Non-incapacitating injury 03/08/15 Sunday Dry Clear Daylight 4:29 PM	Angle	① 29F BISMARCK ND Passenger Car WB Going Straight (Stop) Failed to Yield	② 56M MAX ND Pickup - Van - Utility SB Going Straight	West intersection	↓ ←
3 329286	PDO 06/17/15 Wednesday Dry Cloudy Dusk 9:29 PM	Angle	① 46M IDAHO FALLS ID Passenger Car EB Going Straight (Stop) Disregard Traffic Signs	② 39F LINTO ND Passenger Car SB Going Straight	West intersection	↓ →
4 329476	▶ Non-incapacitating injury 07/01/15 Wednesday Dry Fog / Smoke / Dust Daylight 7:00 AM	Angle	① 19M MINOT ND Passenger Car SB Going Straight Weather	② 51M DICKENSON ND Truck Tractor WB Entering/Leaving Parked (Stop) Weather MV Tran in Other Rdwy	West intersection	↓ ←
5 331159	PDO 08/01/15 Saturday Dry Clear Daylight 5:20 PM	Angle	① 78M LISBON ND Passenger Car EB Going Straight (Stop) Failed to Yield	② 70M GARRISON ND Pickup - Van - Utility SB Going Straight	West intersection	↓ →
6 1008806	PDO 03/04/16 Friday Dry Cloudy Daylight 2:39 PM	Angle	① 33M BISMARCK ND 2-Axle SB Going Straight	② 25M BOLINGBROOK IL Truck Tractor WB Going Straight (Stop) Ran Red Light	West intersection	↓ ←
7 1011562	▶ Incapacitating Injury 05/08/16 Sunday Dry Clear Daylight 11:00 AM	Angle	① 37M MANDAN ND Passenger Car WB Going Straight (Stop) Failed to Yield*	② 26M MINOT AFB ND Pickup - Van - Utility SB Going Straight	West intersection: V1 made NB left turn, then accelerated WB and did not stop at the SB intersection. V1 struck SB V2.	↓ ←
8 1014847	▷ Possible Injury 07/18/16 Monday Dry Clear Dusk 9:11 PM	Angle	① 28M MINOT ND Pickup - Van - Utility EB Going Straight (Stop) Failed to Yield	② 25F HARVEY ND Passenger Car SB Going Straight	West intersection	↓ →
9 1017277	▶ Non-incapacitating injury 09/06/16 Tuesday Dry Clear Daylight 12:54 PM	▲ Angle	① 49F NEW TOWN ND Pickup - Van - Utility WB Going Straight (Stop) Failed to Yield	② 82M GARRISON ND Passenger Car SB Going Straight	West intersection	↓ ←
10 1025755	PDO 01/01/17 Sunday Dry Cloudy Daylight 3:00 PM	Single Veh. (Ditch)	① 39M POWERS LAKE ND Pickup - Van - Utility NB Going Straight Ditch		East intersection	X ↑

Intersection and/or Urban Crash Summary Sheets



Total Crashes: 37 (Sorted by Date)
 City: US 83 & ND 23
 Location: US 83 & ND 23
 Start - End Date: 1/1/2015 - 12/31/2024 (10 Years)

23 USC § 407 Documents
 NDDOT Reserves All Objections

LEGEND
 ▶ Fatal
 ▶ Incapacitating Injury
 ▶ Non-Incapacitating Injury
 ▷ Possible Injury
 ◆ Wet surface
 ❄ Snow, Ice, Slush, Frost
 ▲ Crash related to work zone
 ① Unit number

1. Contributing Factor
 * = alcohol or drugs involved
2. Most Harmful Event
 For single vehicle crashes, the most harmful event is shown in parentheses in the "Type of Collision" column

Crash No.	Crash Severity Date, Day Surface Conditions, Weather Lighting, Time	Type of Collision	① AGE SEX CITY STATE Unit Configuration Movement (traffic control) Contributing Factor¹ Most Harmful Event²	②	Shortened Narrative	Diagram
11	1031895 PDO 04/06/17 Thursday Dry Clear Daylight 6:28 PM	Single Veh. (Post)	① 42M SEATTLE WA Passenger Car EB Going Straight To Fast for Conditions Post		West intersection	→X
12	1035762 PDO 06/23/17 Friday Dry Clear Daylight 9:08 AM	Angle	① 27F DICKINSON ND Pickup - Van - Utility SB Going Straight	② 42M CASSETON ND Truck Tractor WB Going Straight (Stop) Failed to Yield	West intersection	↓ ←
13	1036473 ▶ Incapacitating Injury 07/06/17 Thursday Dry Clear Daylight 6:30 PM	Angle	① 30M NEW TOWN ND Pickup - Van - Utility EB Going Straight (Stop) Failed to Yield	② 16F MINOT ND Passenger Car SB Going Straight	West intersection: V1 EB at 70mph failed to yield and was struck by SB V1.	↓ →
14	1044126 PDO 11/21/17 Tuesday Dry Clear Dark(L) 6:30 AM	Sideswipe (Same Dir.)	① U Hit and Run SB Turning Left	② 28M BURLINGTON ND 3+ Axle SB Going Straight	West intersection	↓↓
15	1046967 ▷ Possible Injury 12/26/17 Tuesday Snow Blowing Snow Dark 3:30 AM	Single Veh. (Ditch) ❄	① 25M MINOT ND Passenger Car EB Going Straight (Stop) To Fast for Conditions* Ditch		East intersection	→X
16	1062609 PDO 09/27/18 Thursday Dry Clear Daylight 3:30 PM	Sideswipe (Opp. Dir.)	① 33F EXELAND WI Truck Tractor NB Turning Left Improper Turn	② 26M MINOT ND Single Unit Truck EB Turning Left (Stop)	East intersection	→ ↑
17	1071138 ▷ Possible Injury 02/04/19 Monday Ice / Snow Clear Daylight 12:30 PM	Angle ❄	① 26M MINOT ND Passenger Car EB Going Straight (Stop) To Fast for Conditions	② 27M NEW TOWN ND Pickup - Van - Utility SB Going Straight Weather	West Intersection	↓ →
18	1080814 PDO 07/09/19 Tuesday Dry Cloudy Daylight 11:30 AM	Sideswipe (Same Dir.)	① 42M BISMARCK ND Pickup - Van - Utility NB Going Straight Improper Overtaking	② 70M MELROSE MN Pickup - Van - Utility NB Changing Lanes	East intersection	↑↑
19	1085502 ▶ Incapacitating Injury 10/14/19 Monday Wet Clear Dark(L) 8:52 PM	Angle ◆	① 47M EDEN PRAIRIE MN Pickup - Van - Utility WB Merging/Diverging (Stop) Failed to Yield	② 40F ALAMO ND Pickup - Van - Utility SB Going Straight	WEST Intersection: V1 WB did not recall if he stopped for the stop sign before proceeding. V1 struck SB V2 on the driver side.	↓ ←
20	1095132 ▶ Fatal 05/28/20 Thursday Dry Clear Daylight 3:27 PM	Angle	① 63F MINOT ND Pickup - Van - Utility SB Going Straight (Oth)	② 44M NEW TOWN ND Passenger Car EB Going Straight (Stop) Ran Red Light	WEST Intersection: V1 SB in right lane. V2 EB did not slow down and failed to yield at the stop sign. V1 struck V2 on the driver's side. D2 sustained fatal injuries.	↓ →

Intersection and/or Urban Crash Summary Sheets



Total Crashes: 37 (Sorted by Date)
 City: US 83 & ND 23
 Location: US 83 & ND 23
 Start - End Date: 1/1/2015 - 12/31/2024 (10 Years)

23 USC § 407 Documents
 NDDOT Reserves All Objections

- LEGEND**
- ▶ Fatal
 - ▶ Incapacitating Injury
 - ▶ Non-Incapacitating Injury
 - ▷ Possible Injury
 - ◆ Wet surface
 - ❄ Snow, Ice, Slush, Frost
 - ▲ Crash related to work zone
 - ① Unit number

- 1. Contributing Factor**
 * = alcohol or drugs involved
- 2. Most Harmful Event**
 For single vehicle crashes, the most harmful event is shown in parentheses in the "Type of Collision" column

Crash No.	Crash Severity Date, Day Surface Conditions, Weather Lighting, Time	Type of Collision	① AGE SEX CITY STATE Unit Configuration Movement (traffic control) Contributing Factor¹ Most Harmful Event²	②	Shortened Narrative	Diagram
21 1096490	▶ Incapacitating Injury 07/14/20 Tuesday Dry Clear Daylight 6:20 PM	Angle	① 25M BISMARCK ND Pickup - Van - Utility SB Going Straight	② 40M WILLISTON ND Pickup - Van - Utility WB Going Straight (Stop) Ran Red Light	WEST Intersection: V1 SB left lane at 70 mph. V2 WB failed to stop at the stop sign and was struck by V1. Both driver and passenger of V2 were treated for life threatening injuries.	↓ ←
22 1103595	▶ Non-incapacitating injury 01/23/21 Saturday Dry Clear Daylight 9:56 AM	Angle	① 61F WILTON ND Passenger Car WB Going Straight (Stop) Failed to Yield	② 42M MINOT ND Pickup - Van - Utility SB Going Straight	WEST Intersection	↓ ←
23 1106216	PDO 03/25/21 Thursday Dry Clear Daylight 2:02 PM	Angle	① 60M KEENE ND Pickup - Van - Utility EB Turning Left (Stop) Failed to Yield	② 55F NORWICH ND Truck Tractor NB Going Straight	EAST Intersection	→ ↑
24 1112514	▶ Non-incapacitating injury 09/17/21 Friday Dry Clear Daylight 6:21 PM	Angle	① 61F NEW TOWN ND Pickup - Van - Utility EB Going Straight (Stop) Failed to Yield	② 55F MINOT ND Pickup - Van - Utility SB Going Straight	WEST Intersection	↓ →
25 1119185	PDO 01/26/22 Wednesday Slush Blowing Snow Daylight 1:35 PM	Single Veh. (Post)	① 28M DOUGLAS ND Passenger Car SB Going Straight Other Post		WEST Intersection	↓ X
26 1122371	▷ Possible Injury 04/22/22 Friday Wet Fog / Smoke / Dust Daylight 4:04 PM	Angle	① 74F MANDAREE ND Passenger Car EB Going Straight (Stop) Failed to Yield	② 26M MINOT ND Pickup - Van - Utility SB Going Straight Weather	WEST Intersection	↓ →
27 1122944	PDO 05/05/22 Thursday Dry Clear Daylight 4:28 PM	Left Turn	① 41M WILLISTON ND Truck Tractor WB Turning Left Improper Turn	② 24F MINOT ND Pickup - Van - Utility EB Stopped (Stop)	EAST Intersection	→←
28 1126187	▶ Incapacitating Injury 08/04/22 Thursday Dry Clear Daylight 8:03 AM	Angle	① 62M BISMARCK ND Unknown Heavy Truck SB Going Straight	② 18M DUNSEITH ND Pickup - Van - Utility EB Going Straight (Stop) Failed to Yield	WEST Intersection	↓ →
29 1128974	▶ Non-incapacitating injury 10/16/22 Sunday Dry Clear Dark(L) 8:22 PM	Sideswipe (Same Dir.)	① 72M MAX ND Pickup - Van - Utility SB Going Straight	② 31M RUGBY ND Pickup - Van - Utility SB Turning Left Improper Turn	WEST Intersection	↓↓
30 1139409	▶ Fatal 05/06/23 Saturday Dry Cloudy Daylight 11:38 AM	Angle	① 25F MINOT AFB ND Pickup - Van - Utility SB Going Straight	② 32M WICHITA KS Passenger Car WB Going Straight (Stop) Failed to Yield	WEST Intersection: V1 SB at 70 mph. V2 WB failed to yield and was struck in the passenger's side by V1.	↓ ←

Intersection and/or Urban Crash Summary Sheets



Total Crashes: 37 (Sorted by Date)
 City:
 Location: US 83 & ND 23
 Start - End Date: 1/1/2015 - 12/31/2024 (10 Years)

23 USC § 407 Documents
 NDDOT Reserves All Objections

- LEGEND**
 ▶ Fatal
 ▶ Incapacitating Injury
 ▶ Non-Incapacitating Injury
 ▷ Possible Injury
 ◆ Wet surface
 ❄ Snow, Ice, Slush, Frost
 ▲ Crash related to work zone
 ① Unit number

- 1. Contributing Factor**
 * = alcohol or drugs involved
2. Most Harmful Event
 For single vehicle crashes, the most harmful event is shown in parentheses in the "Type of Collision" column

Crash No.	Crash Severity Date, Day Surface Conditions, Weather Lighting, Time	Type of Collision	① AGE SEX CITY STATE Unit Configuration Movement (traffic control) Contributing Factor ¹ Most Harmful Event ²	②	Shortened Narrative	Diagram
31 1139355	PDO 05/25/23 Thursday Dry Clear Daylight 1:07 PM	Sideswipe (Same Dir.)	① 18F NEW TOWN ND Passenger Car NB Turning Left (Stop) Failed to Yield	② 45M GARRISON ND Pickup - Van - Utility NB Going Straight	EAST Intersection	↑↑
32 1140358	▶ Fatal 06/14/23 Wednesday Dry Clear Daylight 1:40 PM	Angle	① 57M BISMARCK ND 3+ Axle SB Going Straight	② 57M STEVENSVILLE MT Pickup - Van - Utility EB Going Straight (Stop) Ran Red Light	WEST Intersection: V1 SB in outside lane. V2 EB failed to stop and proceeded into the intersection and was struck by V1.	↓ →
33 1142836	▶ Fatal 08/22/23 Tuesday Dry Clear Daylight 3:51 PM	Angle	① 24M MANDAN ND Pickup - Van - Utility SB Going Straight	② 59F MINOT ND Passenger Car EB Going Straight (Stop) Failed to Yield	WEST Intersection: V1 SB, V2 EB failed to yield the right of way. V1 braked and steered left but was unable to avoid V2. V1 struck driver's side of V2.	↓ →
34 1156248	PDO 08/05/24 Monday Dry Clear Daylight 1:45 PM	Angle	① 16M BISMARCK ND Passenger Car EB Going Straight (Stop) Failed to Yield	② 65M BURLINGTON ND Pickup - Van - Utility NB Going Straight	West intersection	→ ↑
35 1157724	PDO 09/04/24 Wednesday Dry Clear Daylight 6:15 PM	Rear End	① 20F GARRISON ND Passenger Car SB Going Straight	② 58M DICKINSON ND Pickup - Van - Utility SB Going Straight Improper License	West intersection	↓ ↓
36 1157951	▶ Non-incapacitating injury 09/18/24 Wednesday Dry Clear Daylight 2:24 PM	Angle	① 29F WATFORD CITY ND Passenger Car EB Going Straight (Stop) Failed to Yield	② 20F MINOT ND Pickup - Van - Utility SB Going Straight	West intersection	↓ →
37 1162523	PDO 12/23/24 Monday Snow Clear Daylight 2:36 PM	❄ Sideswipe (Same Dir.)	① 63M MINOT ND Pickup - Van - Utility NB Going Straight	② 34M PUEBLA CENTRO MX Unknown Heavy Truck NB Turning Left Improper Turn	EAST Intersection	↑↑
38						
39						
40						